

Environmental and Occupational Health &amp; Safety Unit

# OHS ALERT

## DO NOT USE JLG SCISSOR LIFT MODEL 1932R

In an incident at the Glen Shopping Centre in Victoria in June 2018, a JLG R1932R scissor lift dropped approximately 3 metres without notice while an air con plumber was working on it. Luckily nobody was seriously hurt on this occasion.

This was not an isolated incident. The CFMEU advised members to avoid using this model at the time until it could be determined whether this was a widespread problem or a fault that could be contained and rectified.

Over the two months since the CFMEU initially issued an alert to members to avoid using the JLG 1932R, JLG have confirmed that there is a dangerous flaw with this model and that they should be removed from service immediately.

A letter from JLG confirming the issue with lift model 1932R can be found online at [cg.cfmeu.org.au/jlg1932r](http://cg.cfmeu.org.au/jlg1932r), and should be used to support members' refusal to operate a machine of this model.

If you come across a JLG scissor lift model 1932R please immediately advise your Health and Safety Rep and ensure the scissor lift is tagged out of use, or contact your CFMEU Safety Unit if you have any concerns.



ACT Branch: (02) 6267 1599

SA Branch: (08) 8231 5532

WA Branch: (08) 9228 6900

NSW Branch: (02) 9749 0400

QLD &amp; NT Branch: (07) 3231 4600

VIC TAS Branch: (03) 9341 3444

*Safety is union business.*

**Stand Up. Speak Out. Come Home.**